

# Software Update: Update Pack 2.2UR (UP2.2UR)

## Quick Details

File Name: Update Pack 2.2UR  
 Date Published: September 9th, 2009  
 Download Size: 52MB (UP2.1UR already installed) / 52MB (UP2.0UR already installed) / 301MB (UP2.\* not installed)

## Overview

Update Pack 2.2UR provides the following improvements from the Update Pack 2.1UR.

	Version Before Change	Version After Change	Changes included in Update Pack 2.2UR (UP2.2UR)
Navigation	2.0-UR	2.1UR	<ul style="list-style-type: none"> <li>Corrected the issue of displaying the warning message "Warning. The map data is out of date. Please contact your dealer for an update." Warning message will now display at correct update time.</li> </ul>
YouTube	-	-	<ul style="list-style-type: none"> <li>Improved audio on playback.</li> <li>Modified video lists to display only videos that support the YouTube Embedded Player.</li> </ul>
Browser	-	-	<ul style="list-style-type: none"> <li>Added a new "Add Bookmark" feature to the Bookmark key on the browser toolbar.</li> <li>Added feature to match the Browser language to the language set on Control Panel – Language. Browser may now direct to some URL sites language compatible with the above setting.</li> </ul>
News	-	-	<ul style="list-style-type: none"> <li>Supports "Add News Source" feature to name and add a URL for RSS feeds on the News application.</li> </ul>
Password	-	-	<ul style="list-style-type: none"> <li>Support for a password reset feature to reset a forgotten password on a locked ClarionMiND device. (*1)</li> </ul>
Power Management	-	-	<ul style="list-style-type: none"> <li>Added feature to allow ClarionMiND to enter into the standby state when in Car Mode following the car engine off. The time is set on the Control Panel – Power Management - Standby when Idle menu.</li> </ul>
PDF viewer	-	-	<ul style="list-style-type: none"> <li>Changed the method of switching between full and half screen view from tapping the screen to a screen touch and hold.</li> </ul>
Note Pad	-	-	<ul style="list-style-type: none"> <li>Added feature to switch between full screen and half screen view by a screen touch and hold.</li> </ul>

\*1: Device Password resets may be requested on the "Contact Us" link after login to MyClarion portal site [my.clarion.com](http://my.clarion.com)

- For further details, please refer to the Owner's Manual at <http://my.clarion.com/en-us/html/support>.
- The Update Pack UP2.2UR installs the UP2.0UR and UP2.1UR update if not already installed on the ClarionMiND. For further details of UP2.0UR and UP2.1UR, please refer to *Software Update: Update Pack 2.0UR (UP2.0UR) and Software Update Pack 2.1UR (UP2.1UR)*.
- You cannot uninstall UP2.2UR once it has been installed.

## Software Update Requirements


- A Wi-Fi connection is necessary to execute the software update.
- For information on connecting ClarionMiND to Wi-Fi please refer to the Owner's Manual Chapter 3 (Connecting a network).
- User registration/product registration is necessary to use Portal Sync.
- For registration information please refer to the Owner's Manual Chapter 4 (Registering on the Clarion Portal Site).

## Instructions

Before starting the installation:

- Plug in the AC adaptor (charger).
- Connect ClarionMiND to a Wi-Fi network.  
\*Please refer to Chapter 3 (Connecting to a Network) in the Owner's Manual.
- Close all programs that are running.


1. Tap the Control Panel – Advanced Settings (Expert Settings) – Application Manger to start Application Manager.



2. There are two different ways of performing the update depending on whether the UP2.0UR update is already installed on the ClarionMiND.


Case 1: UP2.0UR or UP2.1UR is already installed:

If the following screen is displayed, go to **Step 2.A.**




Case 2: UP2.0UR or UP2.1UR is not installed:

If the following screen is displayed, go to **Step 2.B.**




2.A. On the Application Manager, verify that the Update Pack UP2.2UR is selected, then tap [OK].  
Go to Step 6.




\* If you want to install *Music Sync* and/or *Traffic* application(s) at the same time, verify that they are also selected, then tap [OK].

\* If the free space on disk is less than 850MB, the message "Not enough free space on disk to process update." may appear and installation may fail to complete. The size of free space can be confirmed on Control Panel – Expert Settings – System Information – Disk.


2.B On the Application Manager select the [Update] tab if not already selected. Tap the [Refresh] button and then select each of the software updates. After all files are selected tap [OK].  
Go to Step 3.



3. Tap [OK] after quitting all running software.



4. Tap [OK] to update.




Application Manager update starts. Application Manager will automatically restart after the update is completed.




- \* Please do not turn the power off during the update.
- \* It may take up to 2 minutes to retrieve the software information.

5. After the restart of Application Manager, the [Update/Install] menu is displayed. Verify that the Update Pack UP2.2UR is selected, then tap [OK].



- \* If you want to install *Music Sync* and/or *Traffic* application(s) at the same time, verify that they are also selected, then tap [OK].

6. Tap [OK] to continue.



- \* Updating process can be more than 30 minutes if the Update Pack UP2.0UR or UP2.1UR is not installed, varying by the speed of internet connection you subscribe and the condition of the connection.
- \* Updating process can be more than 15 minutes if the Update Pack UP2.0UR or UP2.1UR is already installed, varying by the speed of internet connection you subscribe and the condition of the connection.



Update will be started. The system will automatically restart after the installation is completed.



- \* Please do not turn the power off while updating.
- \* The Update Pack(s) includes several large data files. The progress bar may go slowly or sometimes stop while downloading especially in the case where UP2.0UR or UP2.1UR has not been previously installed.


7. After the update and the system has restarted the Home Screen will appear. To confirm the update has completed successfully, launch the Application manager located in the Control Panel on Advanced Settings to confirm the version of the Update Pack is installed as follows.

Launching Application Manager



UP2.2UR will not appear here when update has been completed successfully.

Note :  
Music Sync and/or Traffic will also appear here, if they are not yet installed.



UP2.2UR will appear here when update has been completed successfully.

Note :  
Music Sync and/or Traffic will also appear here when installed.

\* Version of Update Pack can be also confirmed from Control Panel - Advanced Settings - System information - Software


8. Quit the Application Manager.

NOTE:

- After the installation of the Update Pack, the date and time may be changed. Date and time may be set manually or set automatically by initiating Portal Sync or setting the “Adjust by GPS Data” setting on the Date and Time screen.
- Please refer to Owner’s Manual, chapter 7-3 (Date and Time) for more information about setting the date and time.
- Once the Update Pack is installed it cannot be removed.
- The version of the OS, the Update Pack and the additional applications can be confirmed from Control Panel – Advanced Settings - System Information - Software.
- After the installation of the Update Pack, the Keyboard Selection setting in the Navigation application may be changed into “Cyrillic”. Please change it manually if required to the setting previously used. The Keyboard Selection can be changed from the screen Navigation – Settings – Language Settings. Please refer to the Owner’s Manual Chapter 6 (6-4 Language Settings) for the details of Keyboard Selection.



- After the installation of the Update Pack, the icons of the map in the Navigation application may be changed. Please change it manually if required to the setting previously used. The map display can be changed from Navigation – Settings – Display, then change the setting “Change Map display” to “Map Only”. Please refer to the Owner’s Manual Chapter 6 (6-6-2 Display) for the details of Display Settings.



- After the installation of the Update Pack, the Password feature will not be available if the device registration is not completed. For registration information please refer to the Owner's Manual Chapter 4 (Registering on the Clarion Portal Site).
- After the installation of the Update Pack, *Local Search from Google Maps* feature will not be available if the device registration is not completed.
- After the installation of the update pack, RealPlayer key will no longer be available on the options of Quick Information keys set on Control Panel – Mobile Mode Home Screen. For Quick Information please refer to the Owner's Manual Chapter 2-5 (Using the Quick Information Keys) and 7-7 (Mobile Mode Home screen).

**Troubleshooting**

- If the software update fails to complete due to a network problem or power off during the updating process please begin the software update process again.
- If the message "Errors were encountered while downloading packages." appeared and the software update failed to complete, please refer to Owner's Manual chapter 7-12 (Maintenance: Recover RPM database) and then try the update again.